

Ship Name: **ASTRO VENUS**  
IMO Number: **8208414**  
Date Detained: **01/27/2004**  
Port: **Newark, New Jersey**

Ship Type: **Ro-Ro-Cargo Ship**  
Flag: **Panama**  
Class Society: **Nippon Kaiji Kyokai**  
Company(s): Owners, Operators or Managers  
**Chijin Shipping SA**  
**Astro Ship Management Inc.**

Deficiencies: Code - Category  
**0610 - Lifeboats**  
**0620 - Inflatable liferafts**  
  
**0725 - Fixed fire extinguishing installation**  
  
**0999 - Other (Safety In General)**  
  
**2515 - Company responsibility and authority**

Description  
**Starboard lifeboat motor inoperable.**  
**Liferafts are currently in a non-float free arrangement.**  
**Possible leaks and questionable service report on the low-pressure CO2 system.**  
**Ventilation system in engine control room inadequate in way of temporarily installed ducting.**  
  
**Objective evidence discovered during an expanded ISM exam revealed a failure in the SMS. External audit requested.**

---

Ship Name: **ATHINA**  
IMO Number: **7625732**  
Date Detained: **01/11/2004**  
Port: **Reserve, Louisiana**

Ship Type: **Bulk Carrier**  
Flag: **Saint Vincent and the Grenadines**  
Class Society: **Russian Maritime Register of Shipping**  
Company(s): Owners, Operators or Managers  
**Blue Star Line**  
**Bluestar Management Inc,**

Deficiencies: Code - Category  
**0220 - Certificates of competency**

Description  
**The Master, Chief Officer, Second Officer, Third Officer, Second Engineer and Third Engineer do not have receipts from St. Vincent for proof of application for flag state endorsements of their national licenses.**

---

Ship Name: **DAWN**  
IMO Number: **9057197**  
Date Detained: **01/15/2004**  
Port: **Savannah, Georgia**

Ship Type: **Bulk Carrier**  
Flag: **Cyprus**  
Class Society: **Bureau Veritas**  
Company(s): Owners, Operators or Managers  
**Satico Shipping Co. Ltd.**  
**DLS Shipping AB**

Deficiencies: Code - Category  
**0735 - Personal equipment - fire fighting**  
  
**0230 - Number/composition (manning)**

Description  
**Vessel missing one valid/operational SCBA**  
  
**Not manned in accordance with minimum safe manning certificate. Person in Chief Mate position has not Chief Mate's license. All officers are without valid Cyprian endorsements.**

Ship Name: **FLOWER GARDEN**  
IMO Number: **8518895**  
Date Detained: **01/24/2004**  
Port: **Dutch Harbor, Alaska**

Ship Type: **Refrigerated Cargo Carrier**  
Flag: **Panama**  
Class Society: **Nippon Kaiji Kyokai**  
Company(s): Owners, Operators or Managers  
**New Power Ship S.A.**

Deficiencies: Code - Category  
**0610 - Lifeboats**

Description  
**Starboard lifeboat inoperable.**

Ship Name: **GENERAL TYULENEV**  
IMO Number: **8138683**  
Date Detained: **01/27/2004**  
Port: **Port Everglades, Florida**

Ship Type: **General Dry Cargo Ship**  
Flag: **Russian Federation**  
Class Society: **Russian Maritime Register of Shipping**  
Company(s): Owners, Operators or Managers  
**Novoship**

Deficiencies: Code - Category  
**0610 - Lifeboats**

Description  
**Starboard lifeboat davit did not function properly while lowering the starboard lifeboat causing damage to the lifeboat.**

**0610 - Lifeboats**

**Starboard lifeboat was damaged while lowering. Make permanent and proper repairs to the starboard lifeboat.**

Ship Name: **IZAMAYLOVO**  
IMO Number: **8913588**  
Date Detained: **01/16/2004**  
Port: **Corpus Christi, Texas**

Ship Type: **Oil Tankship**  
Flag: **Liberia**  
Class Society: **Det Norske Veritas**  
Company(s): Owners, Operators or Managers  
**Akola Maritime Corp.**  
**Unicom Management Services (Cyprus)**

**Ltd**

Deficiencies: Code - Category  
**0740 - Pumps**

Description  
**Emergency fire pump has crack in discharge piping with excessive leakage.**

Ship Name: **LACONIA**  
IMO Number: **8517578**  
Date Detained: **01/21/2004**  
Port: **New Orleans, Louisiana**

Ship Type: **Bulk Carrier**  
Flag: **Malta**  
Class Society: **Det Norske Veritas**  
Company(s): Owners, Operators or Managers  
**Possidonia Shipping Company Limited**  
**Mantinia Shipping Company S.A.**

Deficiencies: Code - Category  
**0615 - Rescue boats**

Description  
**Starboard lifeboat engine inoperative.**

Ship Name:	<b>LE SHAN</b>	Ship Type:	<b>Bulk Carrier</b>
IMO Number:	<b>9183752</b>	Flag:	<b>China</b>
Date Detained:	<b>01/14/2004</b>	Class Society:	<b>China Classification Society</b>
Port:	<b>Houston, Texas</b>	Company(s):	<u>Owners, Operators or Managers</u> <b>Guang Zhou Ocean Shipping Co. Pacific Ocean Singapore</b>

Deficiencies:	<u>Code - Category</u> <b>0945 - Emergency lighting, etc</b>	<u>Description</u> <b>Master and navigation officers unfamiliar with the ships automation remote control system.</b>
	<b>2015 - Communication</b>	<b>Master and navigation officers are unable to communicate in English.</b>
	<b>2050 - Operation of machinery</b>	<b>Discrepancies between English and Chinese version of the ships automation remote control system; ships automation remote control system is suspect and possibly malfunctioning.</b>

---

Ship Name:	<b>LIMAN</b>	Ship Type:	<b>Bulk Carrier</b>
IMO Number:	<b>9053775</b>	Flag:	<b>Malta</b>
Date Detained:	<b>01/05/2004</b>	Class Society:	<b>Det Norske Veritas</b>
Port:	<b>Westwego, Louisiana</b>	Company(s):	<u>Owners, Operators or Managers</u> <b>Asp-Seascot Ship Management Ltd. Linam Shipping Company Ltd.</b>

Deficiencies:	<u>Code - Category</u> <b>1499 - Other (Prop. &amp; Aux. Machinery)</b>	<u>Description</u> <b>The vessel's 3 auxiliary generators are not equipped with a fuel oil leakage detection arrangement. The double jacketed high pressure fuel pump piping for the generators is equipped with the fittings for installation of the system but not installed.</b>
	<b>0220 - Certificates of competency</b>	<b>The vessel's Second Engineer does not have a flag state endorsement to this national license or documentary proof one has been applied for.</b>

Ship Name:	<b>SCAN NORDIC</b>	Ship Type:	<b>Ro-Ro-Cargo Ship</b>
IMO Number:	<b>7931985</b>	Flag:	<b>Norway</b>
Date Detained:	<b>01/29/2004</b>	Class Society:	<b>Lloyd's Register of Shipping</b>
Port:	<b>Philadelphia, Pennsylvania</b>	Company(s):	<u>Owners, Operators or Managers</u> <b>Scandinavian Shipping Invest AS</b>

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	<b>0945 - Emergency lighting, etc</b>	<b>Emergency generator unable to be started by secondary means.</b>
	<b>2110 - Oil/oily mixtures machinery spaces</b>	<b>Vessel has 3 or 4 drums of oil that are catching oil form various lube oil trays located in engine room.</b>
	<b>2199 - Other (MARPOL Related Operational Def.)</b>	<b>Vessel has oil soaked lagging located aft of main engine, starboard side, top &amp; bottom and oil soaked lagging around purifiers in engine room, port side.</b>
	<b>1720 - Control of discharge of oil</b>	<b>Vessel has numerous leaks throughout the engineroom as noted on handwritten detention report. These include f/o filter gasket for main engine, l/o leak on no. 3 generator, oil leak in starboard air compressor, hydraulic leak for side loader and lift.</b>
	<b>2199 - Other (MARPOL Related Operational Def.)</b>	<b>Vessel SOPEP procedures were not followed as per the bunker oil spill that occurred on 28Jan04, ie. Report not filled out, notifications not completed, etc.</b>
	<b>2510 - Safety and environmental policy</b>	<b>Objective evidence revealed that SMS failed as indicated by Master's unfamiliarity with the SMS, not following bunker procedures, no drill documentation, no pre-arrival checklist, monthly meeting not conducted and numerous missing pieces of the SMS.</b>
	<b>1710 - Oil record book</b>	<b>Oil record book not filled out properly.</b>
	<b>1299 - Other (Load Lines)</b>	<b>Forward deck storage has 5-6 feet of standing water.</b>
	<b>1240 - Cargo and other hatchways</b>	<b>Aft hatch hinge for deck storage is broken and rotted.</b>

Ship Name:	<b>SPRING DRAKE</b>	Ship Type:	<b>Bulk Carrier</b>
IMO Number:	<b>9194385</b>	Flag:	<b>Panama</b>
Date Detained:	<b>01/30/2004</b>	Class Society:	<b>Nippon Kaiji Kyokai</b>
Port:	<b>Portland, Oregon</b>	Company(s):	<u>Owners, Operators or Managers</u> <b>Grus Line Shipping S.A.</b>

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	<b>1730 - Oily-water separating equipment</b>	<b>Oily Water Separator inoperable.</b>
	<b>1799 - Other (MARPOL Annex I)</b>	<b>Prove proper operation of the waste oil incinerator.</b>

Ship Name:	<b>VIT FALK</b>	Ship Type:	<b>Oil Tankship</b>
IMO Number:	<b>9262091</b>	Flag:	<b>Italy</b>
Date Detained:	<b>01/07/2004</b>	Class Society:	<b>Registro Italiano Navale</b>
Port:	<b>Bonnet Carre, Louisiana</b>	Company(s):	<u>Owners, Operators or Managers</u> <b>L.G.R. DI Navigazione Spa</b> <b>TORM Waterfront Tankers</b>

Deficiencies: Code - Category  
**0220 - Certificates of competency**  
  
**2530 - Resources and Personnel**

Description  
**The Third Engineer does not have a flag state endorsement for his license and his proof of application expired on 18 Nov 2003.**  
  
**Objective evidence was found that the company and vessel were not following the guidance of their Safety Management System, which requires the vessel to be manned with appropriately certificated personnel.**

---

---

Ship Name:	<b>ZEPHYROS</b>	Ship Type:	<b>General Dry Cargo Ship</b>
IMO Number:	<b>7378822</b>	Flag:	<b>Saint Vincent and the Grenadines</b>
Date Detained:	<b>01/23/2004</b>	Class Society:	<b>American Bureau of Shipping</b>
Port:	<b>New Orleans, Louisiana</b>	Company(s):	<u>Owners, Operators or Managers</u> <b>Aubrun Shipping Corporation</b> <b>Albamar Shipping Co. S.A</b>

Deficiencies: Code - Category  
**0220 - Certificates of competency**  
  
**2515 - Company responsibility and authority**

Description  
**The vessel does not have a qualified Second Engineer (III/2) as per minimum Safe Manning Document. The vessel's current Second Engineer has only Officer of an Engineering Watch (III/1) national license and flag state endorsement.**  
  
**Objective evidence was found that the vessel's SMS failed in ensuring that the vessel is manned in accordance with the Minimum Safe Manning Document and that all officers have the appropriate flag state endorsements.**

---

---

Ship Name:	<b>ZETAGAS</b>	Ship Type:	<b>Gas Carrier (Non-Specified)</b>
IMO Number:	<b>8111855</b>	Flag:	<b>Netherlands Antilles</b>
Date Detained:	<b>01/23/2004</b>	Class Society:	<b>Germanischer Lloyd</b>
Port:	<b>Houston, Texas</b>	Company(s):	<u>Owners, Operators or Managers</u> <b>Zetagas Shipping Co.</b> <b>B. V. United Gas Carriers</b>

Deficiencies: Code - Category  
**0720 - Fire fighting equipment**  
**0745 - Fire-dampers remote control, etc.**

Description  
**Fixed gas detection system not installed.**  
**Ventilation dampers in motorroom and compressor room frozen.**